

Dear Valued Customers

October, 2026

IAI Corporation

Sales department

Notice for discontinuation of RCP2-RA10C series

Thank you for your continued support of IAI Corporation. We appreciate your loyal patronage towards the RCP2-RA10C(RCP2-RFA) series, but these products will be discontinued on October, 2027. We apologize for any inconvenience that this may cause you, and we appreciate your understanding.

Best Regards

Details

- | | | |
|-------------------------------|---|---|
| 1. Applicable Models | : | RCP2-RA10C
RCP2W-RA10C (Dust-Proof/Splash-Proof Type)
RCP2-RFA
RCP2-RFW (Dust-Proof/Splash-Proof Type)
(Including special specification products) |
| 2. Reason for discontinuation | : | The RCP2-RFA(Current Model Number: RCP2-RA10C) series was released in January 2005.
Some parts of the motor for these products have been discontinued and it is difficult to obtain a stable supply of them. |
| 3. End of Order Date | : | Production will end with orders received by October 6th, 2027.
※Final shipment is made within approx. 2 months after final order placed.
※Special-specification products based on this model will also be discontinued. |
| 4. End of Service Target | : | Until October 2nd, 2037
However, we may stop service once we are out of parts in stock for the discontinued products before the end of the service period. |

Website URL: <https://www.intelligentactuator.com/list-of-discontinuing-and-obsolete-products/>

- | | | |
|----------------------|--|---|
| 5. Replacement Model | | RCP5-RA10C(RCP5W-RA10C Dust-Proof/Splash-Proof Type) series
※Please note that there is no compatibility regarding external dimensions or location and size of mounting holes on the bottom face.
(Mounting holes on the rod-side flange has compatibility.)
Please refer to the catalog for details. |
|----------------------|--|---|

Thank you